

# 1984 - 1996 Corvette: Water Leakage: Preventing Water Leaks Into the Interior Near Side Windows

On the upper right hand corner of each side glass near the top of the windshield, you will see a triangular shaped piece of black plastic. Gently try to bend these pieces down a bit in order to crimp the rubber down a little more. This may help.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1984-1996-corvette-water-leakage-preventing-water-leaks-into-the-interior-near-side-windows-666.html>